

















## JUNTAS DE TURBINA / DIVERSAS

 <p>72021 F / FF</p>	 <p>72024</p>	 <p>72083</p>
<p>Junta de escape do caminhão Man TDX motor VW-28440/29440</p>	<p>Junta do coletor de escape caminhão Mann VW-28.280 - 07W131797</p>	<p>Junta do modulo atuador ZF AS-Tronic 12AS / 16AS Man / Iveco / Mercedes / Daf / Renault - 0501323922</p>
 <p>72086</p>	 <p>72173 FF</p>	 <p>72174 FF</p>
<p>Junta do modulo atuador ZF AS-Tronic 12AS / 16AS Man / Iveco / Daf / Mercedes / Renault - 0501316322</p>	<p>Junta base da turbina Borg Warner R25-K-03-B2- Bi turbo- Iveco Daily /Ducato multijet/Man 4/6 cils - QVW- 24280/13190/3128</p>	<p>Junta para mesa de turbina Man 17280 / 24280 - bi turbo</p>
 <p>72272 F</p>	 <p>72275 NS</p>	
<p>Junta do caracol bi turbo R2S B1- Borgh - Iveco / VW</p>	<p>Junta de recirculação de gases Mann - VW 28-280 bi turbo - 07W131797B</p>	

## JOGO DE JUNTAS DE CÂMBIO

 <p>50082 NA</p>	 <p>50084 NA</p>	 <p>50085 NA</p>	 <p>11772 NA</p>				
 <p>50083 NA</p>	 <p>50081 NA</p>	 <p>50192 NA</p>	 <p>48994 NA</p>				
<p><b>72080 NA      Jogo de juntas de câmbio do Iveco / Man - 9S1110-TD / 9S1310</b></p>							
N/Número	Original	Descrição	QT	N/ Número	N/Original	Descrição	QT
11772 NA	TJG301865B	Junta da tomada de força	01	50083 NA		Junta lateral	01
48994 NA	0002642980	Junta	01	50084 NA		Junta da tampa	01
50081 NA	1324307058	Junta lateral	01	50085 NA		Junta da moringa	01
50082 NA	0501321879	Junta da tampa do câmbio	01	50192 NA		Junta da caixa	01